



E711

DORMER


- Machine Taps, Interrupted Threads
- Maschinen-Gewindebohrer
- Machinetappen, onderbrokendraad
- Taraulds machine
- Machos de máquina, dientes alternos
- Macho de Máquina, Rosca Interrompida



E711



- 1.3 1.4
- 1.1 1.2 1.5 3.1 3.2 3.3 3.4 6.2 7.3 7.4 8.1

NPT	TPI	d ₁ nom mm	l ₁ mm	l ₂ mm	d ₂ Ø mm	□ a mm	l ₃ mm		l ₄ mm	z	e-Code
1/8	27	10,29	70	19	11,1	8,3	10	8.5	19	5	E7111/8
1/4	18	13,72	75	27	14,3	10,7	11	11	27	5	E7111/4
3/8	18	17,15	80	27	17,8	13,5	13	14.5	27	5	E7113/8
1/2	14	21,33	100	35	17,5	13,1	16	18		5	E7111/2
3/4	14	26,67	105	35	23,0	17,2	17	23		5	E7113/4
1	11.5	33,40	115	43	28,6	21,4	21	29		5	E7111
1.1/2	11.5	48,26	135	43	38,1	28,6	25	44		7	E7111.1/2